



HOT MELT



Hot Melt connectors are pre-loaded with adhesive, so there is no mixing of epoxy and no syringe required. Termination is easy; simply insert the connector into the oven, allow it to reach temperature while preparing the fibre end, remove the connector from the oven, fit the fibre and allow to cool before polishing. The Universal Hot Melt termination kit includes all the tools necessary for preparing and terminating the fibre, including the oven and a quality inspection microscope.

Termination Equipment and Tooling:

Product	Order Code
Universal Hot Melt Termination kit, 230Volt	6361
SC Hot Melt Connector Holder, pack of 4	SP00508
Hot Melt One-Step Polishing Machine, 6851 E	6851
Cooling stand	6191
ST Hot Melt Connector Holder, pack of 6	6190
Crimp Tool	78807381690
One-Step Lapping Film, green, 2µm, hand polishing	6192A
Lapping Film for Polishing Mashine, green, 2µm	6192B
Universal Polishing Jig	8892
Polishing Pad	78807375254
240 volt Hot Melt oven*	GE7000-32818
110 volt Hot Melt oven*	6312



Both 240V and 110V ovens are now CE certified

Product Description	Order Code
ST multimode Hot Melt Connector with black boot	6100B
ST singlemode Hot Melt Connector with yellow boot	8100YS
SC multimode Hot Melt Connector with white boot	6300W
SC singlemode Hot Melt Connector with white boot	8300

